

4

BODYWORK (PANELS)

WHEN ITS GONE ITS GONE

<u>Part Description</u>	<u>Price (+VAT)</u>	<u>Part number</u>
ASHTRAY MOUNT IN REAR POCKET - MK1/2 . LH	6.75	11.37.01.03
ASHTRAY MOUNT IN REAR POCKET MK1/2 - RH	6.75	11.37.01.04
BONNET FRONT LIP (MOUNTS GRILLE TOP SURROUND)	8.25	MS3
DOOR FRAME FRONT PART MK3 - LH	18.00	MSL43L
DOOR HINGE REPAIR PANEL + CHECKSTRAP BRACKET - LH	13.65	MSL7L
DOOR OUTER HINGE PANEL (EXTERIOR HINGES) RH	11.10	MS8R
DOOR PILLAR PART+ SWITCH HOLE - MK1/2/VAN ETC . RH	13.00	11.14.10.68
DOOR STEP + LOWER PANEL - CLUBMAN ESTATE . LH ^	20.00	MS48L
FRONT FLOOR WITH INNER SILL - LH . 1991-00	23.10	MSL25L
GRILLE - MK2 TYPE . CHROME . STANDARD	50.00	ALA6654MS
INNER SILL REPAIR PANEL - LH	14.85	MS27L
INNER WING - 1969-00 SALOON TYPE . RH ^	130.00	ABD36006
INNER WING - 1993-97 TYPE . LH ^	95.00	ABD36007
INNER WING - FRONT HALF - MK1/2/VAN/PICKUP . RH	35.00	11.21.00.98
INNER WING REAR REPAIR - MK1/2/VAN/PICKUP . LH	21.00	11.21.00.87
OUTER SILL - NARROW 4 VENT OE TYPE (1959-69) . LH	20.00	11.32.00.01
REAR ARCH TO DOOR REPAIR - VAN/ESTATE/PICKUP . LH	9.00	21.14.00.27
REAR ARCH TO DOOR REPAIR VAN/ESTATE/PICKUP . RH	9.00	21.14.00.28
REAR FLOOR REPAIR - RH	25.00	MS26R
REAR FLOOR REPIAR - LH	25.00	MS26L
REAR PILLAR REINFORCEMENT PLATE - LH . N.O.S	1.50	14A6608
REAR PILLAR REINFORCEMENT PLATE 1959-64 .RH . N.O.S	1.50	14A6607
REAR QUARTER PANEL - 1969 ON . LH	30.00	MS18L
REAR QUARTER PANEL LINER RETAINER - MK1/2 . LH ^	15.00	11.14.01.17
REAR SUBFRAME MOUNT STIFFENER (BOOT FLOOR) - LH	3.50	11.41.00.47
REAR SUBFRAME MOUNT STIFFENER (BOOT FLOOR) - RH	3.50	11.41.00.48
REAR VALANCE - CENTRE SECTION . VAN/PICKUP/ESTATE	15.00	MS23
REPAIR PANEL - REAR ARCH TO DOOR . SALOON . RH	9.00	11.14.10.08
STIFFENER PANEL - INNER SILL VAN ET . LH OE (14A9025)	15.00	31.32.08.03
SUBFRAME CLOSING PANEL IN REAR POCKET . LH	5.00	11.41.07.03
SUBFRAME CLOSING PANEL SEGMENT - RH	3.22	11.41.08.04
SUBFRAME CLOSING PANEL SEGMENT . LH	3.50	11.41.08.03
VAN REAR CORNER REPAIR - LH (MS50L)	8.00	21.14.00.17
VAN REAR CORNER REPAIR - RH (MS50R)	8.00	21.14.00.18
WINDSCREEN LOWER REPAIR PANEL - NON ORIGINAL	30.00	HMP441001Z
WING - NON GENUINE . LH	51.00	MS1L