

## 1 BODYWORK (PANELS) USED PARTS

<u>Part Description</u>	<u>Price (+VAT)</u>	<u>Part number</u>
BONNET - CLUBMAN . S/H (FROM)	50.00	U.CZH2609
PARCEL SHELF - PRE SPEAKER TYPE . S/H	35.00	U.14A6459
VAN/ESTATE REAR DOOR S/H . LH (Ask)	50.00	U.14A8097
VAN/ESTATE REAR DOOR S/H . RH (Ask)	50.00	U.14A8096
WINDOW FRAME - ESTATE . LH . S/H (Ask for stock details)	25.00	U.14A9625

## 2 BODYWORK (PANELS) NEW PARTS

<u>Part Description</u>	<u>Price (+VAT)</u>	<u>Part number</u>
AIR HOSE BLANKING PLATE ON BULKHEAD - MK1/2/VAN Etc.	7.50	11.25.05.05
BATTERY BOX	15.45	MS31
BOLT - M8 X 20MM (Holds teardrop on replacement front panel)	0.20	SH108201
BOLT - M8 X 70 (For replacement rear subframe panel)	0.50	MS51S
BONNET - 1969-97 . NON ORIGINAL	89.75	MSL2
BONNET - 1969-97 . ORIGINAL (HERITAGE)	145.06	CZH455
BONNET FRONT LIP ( MOUNTS GRILLE TOP SURROUND )	8.25	MS3
BONNET OUTER SKIN ONLY	55.90	MS2S
BOOT FLOOR ASSEMBLY - NO BATTERY BOX . HERITAGE	161.64	ALA5513
BOOT FLOOR CORNER - LH	10.50	MS24L
BOOT FLOOR CORNER - RH	10.50	MS24R
BOOT FLOOR REAR SECTION	18.00	MS54
BOOT HINGE PANEL	13.50	MS20
BOOT LID - (MK 3) 1969-00 . NON GENUINE	58.00	MS19
BOOT LID CONVERSION TO MK1 STYLE	15.00	MS19K
BRACKET - BONNET RELEASE CABLE TO PARCEL SHELF ^	3.00	ASU360100
BRACKET - REAR WHEEL ARCH / BOOT FLOOR (14A6609) - RH	7.50	11.41.04.04
BRACKET - REAR WHEEL ARCH / BOOT FLOOR (14A6610) - LH	7.50	11.41.04.03
COMPANION BOX BASE - SALOON . RH	6.00	14A8994
COMPANION BOX BASE- SALOON . LH	6.00	14A8995
COMPANION BOX LOWER REPAIR MK1/2 - LH	13.50	11.37.00.17
COMPANION BOX LOWER REPAIR MK1/2 - RH	13.50	11.37.00.18
CROSSMEMBER - PRE ROD CHANGE (1959-74)	46.00	14A9533
CROSSMEMBER - ROD CHANGE TYPE	44.85	CZH2675
DIAGONAL STIFFENER - FRONT PANEL (For use with oil cooler)	4.00	24A1918
DOOR BOTTOM REPAIR - LH . WIND UP WINDOW TYPE	9.37	MS33L
DOOR BOTTOM REPAIR - MK1/ VAN / PICKUP . LH	30.00	MS12LL
DOOR BOTTOM REPAIR - MK1/ VAN / PICKUP . RH	30.00	MS12LR
DOOR BOTTOM REPAIR - RH . WIND UP WINDOW TYPE	9.37	MS33R
DOOR BOTTOM REPAIR MK3 . LH	15.54	MS34L
DOOR BOTTOM REPAIR MK3 . RH	15.54	MS34R
DOOR HINGE PANEL (A Panel) - INTERNAL HINGES . LH	9.90	MS9L
DOOR HINGE PANEL (A Panel) - INTERNAL HINGES. RH	9.90	MS9R
DOOR HINGE PANEL (A Panel) - MK3 . GENUINE . RH	18.46	ALA5660
DOOR HINGE PANEL (A Panel) - MK3 . GENUINE . LH	18.46	ALA5661
DOOR HINGE PANEL SUPPORT (BASIC) - RH	6.63	MSL41R
DOOR HINGE PANEL SUPPORT (BASIC) - LH	6.63	MSL41L
DOOR HINGE PANEL SUPPORT WITH AIR VENT PART LH	18.00	MSL42L
DOOR HINGE PANEL SUPPORT WITH AIR VENT PART RH	18.00	MSL42R
DOOR HINGE REPAIR PANEL + CHECKSTRAP BRACKET - LH	7.65	MSL7L
DOOR HINGE REPAIR PANEL+ CHECKSTRAP BRACKET - RH	7.65	MSL7R
DOOR INNER HINGE PANEL (EXTERIOR HINGES) - LH	19.67	MS7L
DOOR INNER HINGE PANEL (EXTERIOR HINGES) - RH	19.67	MS7R
DOOR OUTER HINGE PANEL ( EXTERIOR HINGES) RH	9.00	MS8R
DOOR OUTER HINGE PANEL (EXTERIOR HINGES) LH	9.00	MS8L
DOOR PILLAR PART+ SWITCH HOLE - MK1/2/VAN ETC . LH	14.50	11.14.10.67
DOOR PILLAR PART+ SWITCH HOLE - MK1/2/VAN ETC . RH	14.50	11.14.10.68
DOOR SKIN - SLIDING WINDOW TYPE . LH	29.85	MS12L
DOOR SKIN - SLIDING WINDOW TYPE . RH	29.85	MS12R

## Parts prices (+VAT)

DOOR SKIN - WIND UP WINDOW TYPE . LH	28.65	MS11L
DOOR SKIN - WIND UP WINDOW TYPE . RH	28.65	MS11R
DOOR SKIN MK3 - NO UPPER STIFFENER (Grass track) . LH	24.00	MS11LG
DOOR SKIN MK3 - NO UPPER STIFFENER (Grass track) . RH	24.00	MS11RG
DOOR SKIN OUTER BOTTOM REPAIR MK3 - LH	6.98	MSP011L
DOOR SKIN OUTER LOWER REPAIR - RH	6.98	MSP011R
DOOR STEP + LOWER PANEL - CLUBMAN ESTATE . LH	30.48	MS48L
DOOR STEP + LOWER PANEL - CLUBMAN ESTATE . RH	30.48	MS48R
DOOR STEP + LOWER PANEL - SALOON . LH	33.38	MSL28L
DOOR STEP + LOWER PANEL - SALOON . RH	33.38	MSL28R
DOOR STEP + PANEL - MK1/2 SALOON . LH *	0.00	MS28L
DOOR STEP - DEEP VERSION . EXT. HINGE TYPE . LH	35.10	11.14.00.39
DOOR STEP - DEEP VERSION . EXT. HINGE TYPE . RH	35.10	11.14.00.40
DOOR STEP PANEL WITH ENDS - 1969-00 . LH	10.35	MS16L
DOOR STEP PANEL WITH ENDS - 1969-00 . RH	10.35	MS16R
ENGINE STEADY BAR LOWER BRACKET TO BULKHEAD	5.00	14A6730
FLOOR - SILL TO 1ST GROOVE . 1959-69 SALOON . RH ^	80.00	11.33.01.28
FLOOR - SILL TO 1ST GROOVE 1959-69 SALOON . LH ^	80.00	11.33.01.27
FLOOR HALF WITH INNER SILL - SALOON . LH	54.00	11.34.04.17
FLOOR HALF WITH INNER SILL - SALOON . RH	54.00	11.34.04.18
FLOOR HALF WITH INNER SILL - VAN/ESTATE/PICKUP . LH	54.00	21.34.04.17
FLOOR HALF WITH INNER SILL - VAN/ESTATE/PICKUP . RH	54.00	21.34.04.18
FRONT FLOOR + INNER SILL - LH . RESTO. QUALITY .1961-91	19.50	MS25L
FRONT FLOOR + INNER SILL - RH . RESTO. QUALITY . 1961-91	19.50	MS25R
FRONT FLOOR WITH INNER SILL - LH . 1991-00	18.20	MSL25L
FRONT FLOOR WITH INNER SILL - RH . 1991-00	18.20	MSL25R
FRONT PANEL - 1977-97 . NO BUMPER LIP	36.00	MS4G
FRONT PANEL - MK1/3 (1959-77)	56.85	MS4E
FRONT PANEL - MK4 (1977-97)	46.80	MS4L
FRONT PANEL 1997 ON - NON GENUINE	56.16	ASJ360070Z
FRONT PANEL CONVERSION TO VAN / PICKUP TYPE	27.50	AAM1106K
HEADLAMP PANEL - CLUBMAN . LH	6.00	MS56L
INNER SILL REPAIR PANEL - LH	10.35	MS27L
INNER SILL REPAIR PANEL - RH	10.35	MS27R
INNER WING - 1969-00 SALOON TYPE . RH	129.26	ABD36006
INNER WING - FRONT HALF (+ ROUND FAN) 1992-97 - LH	35.00	15.21.00.97
INNER WING - FRONT HALF - MK1/2/VAN/PICKUP . RH	35.00	11.21.00.98
INNER WING - FRONT HALF . 1959-92 . LH	35.00	13.21.00.97
INNER WING - FRONT HALF . SALOON 1969-00 . RH	35.00	13.21.00.98
INNER WING LOWER REPAIR - LH	13.00	11.21.00.57
JACKING POINT - FULL ASSEMBLY. LH	7.00	14A8375
JACKING POINT - FULL ASSEMBLY. RH	6.50	14A8374
JACKING POINT ONLY - LH ^	1.45	14A8337
JACKING POINT ONLY - RH ^	1.45	14A8336
LOWER CORNER REPAIR UNDER REAR LIGHT - LH	7.65	MS20XL
LOWER CORNER REPAIR UNDER REAR LIGHT - RH	7.65	MS20XR
OUTER SILL - NARROW 4 VENT OE TYPE (1959-69) . LH	18.00	11.32.00.01
OUTER SILL - NARROW 4 VENT OE TYPE (1959-69) . RH	18.00	11.32.00.02
OUTER SILL - NARROW 6 VENT OE TYPE (1969-00) . LH	19.00	14A9535
OUTER SILL - NARROW 6 VENT OE TYPE (1969-00) . RH	19.00	14A9534
OUTER SILL - SALOON . WIDE . LH	15.45	MS55L
OUTER SILL - SALOON . WIDE . RH	15.45	MS55R
OUTER SILL - VAN / PICKUP / ESTATE . WIDE . LH	18.45	MS58L
OUTER SILL - VAN/ PICKUP/ESTATE . WIDE . RH	18.45	MS58R
OUTER SILL VAN/ESTATE/PICKUP LH - LATE OE TYPE ^	25.00	14A9027
OUTER SILL VAN/ESTATE/PICKUP RH - LATE OE TYPE ^	25.00	14A9026
PICKUP REAR BODYSIDE - LH	110.00	14A7556
PICKUP REAR BODYSIDE - RH	115.00	14A7555
PICKUP REAR LAMP PANEL LOWER REPAIR - LH	5.50	41.14.01.17
PICKUP REAR LAMP PANEL LOWER REPAIR - RH	5.50	41.14.01.18
REAR ARCH TO DOOR REPAIR - VAN/ESTATE/PICKUP . LH	9.00	21.14.00.27
REAR ARCH TO DOOR REPAIR VAN/ESTATE/PICKUP . RH	9.00	21.14.00.28
REAR CORNER SEAM COVER - VAN/ESTATE/PICKUP	5.50	BMP131
REAR CORNER VALANCE - VAN / ESTATE / PICKUP . LH	9.90	MS52L
REAR CORNER VALANCE - VAN / ESTATE / PICKUP . RH	9.90	MS52R
REAR DOOR STEP - VAN / ESTATE / PICKUP	14.36	MS53

## Parts prices (+VAT)

REAR FLOOR - SALOON . LH (Includes rear pocket part)	24.00	11.34.04.67
REAR FLOOR - SALOON . RH ( Includes rear pocket part )	24.00	11.34.04.68
REAR FLOOR - VAN/ESTATE/PICKUP . LH	27.00	21.34.04.67
REAR FLOOR - VAN/ESTATE/PICKUP . RH	27.00	21.34.04.68
REAR QUARTER PANEL - 1969 ON . LH	28.50	MS18L
REAR QUARTER PANEL - 1969 ON . RH	28.50	MS18R
REAR QUARTER PANEL - MK1/2 . RH	67.50	MS17R
REAR QUARTER PANEL LINER RETAINER - MK1/2 . LH	16.64	11.14.01.17
REAR SEAM FINISHER - VAN/ESTATE/PICKUP	5.00	BMP130
REAR SEAM FINISHER STRIP - ARCH TO VALANCE (Saloon)	2.95	BMP129
REAR SUBFRAME MOUNT STIFFENER (BOOT FLOOR) - LH	3.50	11.41.00.47
REAR SUBFRAME MOUNT STIFFENER (BOOT FLOOR) - RH	3.50	11.41.00.48
REAR SUBFRAME MOUNTING END REPAIR PANEL - LH	9.00	MS51L
REAR SUBFRAME MOUNTING END REPAIR PANEL - RH	9.00	MS51R
REAR SUBFRAME MOUNTING PANEL - OE SPEC . LH	13.75	11.32.02.17
REAR SUBFRAME MOUNTING PANEL - OE SPEC . RH	13.75	11.32.02.18
REAR SUBFRAME MOUNTING PANEL - SALOON .1959-92	45.00	11.32.02.00
REAR SUBFRAME MOUNTING PANEL - VAN/PICKUP . LH	16.80	31.32.02.17
REAR SUBFRAME MOUNTING PANEL - VAN/PICKUP . RH	16.80	31.32.02.18
REAR VALANCE - SALOON	12.30	MS22
REAR VALANCE CORNER - SALOON . LH	7.35	MS40L
REAR VALANCE CORNER - SALOON . RH	7.35	MS40R
REAR VALANCE CORNER AS OE - LH	15.75	ALA8623
REAR VALANCE CORNER AS OE - RH	15.75	ALA5528
REAR WHEEL ARCH LOWER CORNER - RH (MSP017R)	5.00	11.14.00.58
REAR WHEELARCH PANEL - LH	37.50	MS398L
REAR WHEELARCH PANEL - RH	37.50	MS398R
REPAIR PANEL - REAR ARCH TO DOOR . SALOON . LH	9.00	11.14.10.07
REPAIR PANEL - REAR ARCH TO DOOR . SALOON . RH	9.00	11.14.10.08
SEAM FINISHER - FRONT	4.80	BMP127
SEAM FINISHER - REAR . LH	4.80	BMP125
SEAM FINISHER - REAR . RH	4.80	BMP124
STIFFENER PANEL - INNER SILL . VAN / PICKUP . RH ^	14.04	31.32.08.04
STIFFENER PANEL - INNER SILL . VAN / PICKUP . LH ^	14.04	31.32.08.03
SUBFRAME CLOSING PANEL - VAN / PICKUP RH	7.50	31.41.07.04
SUBFRAME CLOSING PANEL - VAN / PICKUP. LH	7.50	31.41.07.03
SUBFRAME CLOSING PANEL IN REAR POCKET . LH	4.31	11.41.07.03
SUBFRAME CLOSING PANEL IN REAR POCKET . RH	4.31	11.41.07.04
SUBFRAME CLOSING PANEL SEGMENT - RH	3.22	11.41.08.04
SUBFRAME CLOSING PANEL SEGMENT . LH	3.22	11.41.08.03
SUPPORT FOR CABLE / PIPE - 4 FINGER . SALOON (ALA5527) ^	2.75	11.31.05.05
VAN REAR CORNER REPAIR - LH	8.00	21.14.00.17
VAN REAR CORNER REPAIR - RH	8.00	21.14.00.18
WINDSCREEN CORNER PANEL - LH	9.00	MS6L
WINDSCREEN CORNER PANEL - RH	9.00	MS6R
WINDSCREEN CORNER SUPPORT PANEL - LH	8.40	MS6XL
WINDSCREEN CORNER SUPPORT PANEL - RH	8.40	MS6XR
WINDSCREEN LOWER REPAIR PANEL - HERITAGE	119.65	HMP441001
WINDSCREEN LOWER REPAIR PANEL - NON ORIGINAL	41.85	HMP441001Z
WING - 97 ON (NO AERIAL HOLE) . GENUINE . LH	74.36	ASB360010
WING - NON GENUINE . LH	35.88	MS1L
WING - NON GENUINE . RH	35.88	MS1R
WING CLUBMAN LH - HERITAGE	104.90	CZH409
WING CLUBMAN RH - HERITAGE	104.90	CZH408
WING WITH REPEATER HOLE - GENUINE . LH	83.52	BMP455
WING WITH REPEATER HOLE - GENUINE . RH	83.52	BMP454
WING WITH REPEATER HOLE - NON GEN. LH	35.88	BMP455MS
WING WITH REPEATER HOLE - NON GEN. RH	35.88	BMP454MS
WING WITH REPEATER HOLE NO AERIAL - NON GEN .LH	35.88	ASB360010Z